ENEC LICENSE

License No. ENEC-04084

Page 1/3

Date of Issue 2022-06-27

License Holder BULGIN LTD

200 SCIENCE PARK

MILTON RD CAMBRIDGE CB4 0GZ

UNITED KINGDOM

Production site BULGIN TUNISIE

13 RUE 62128

ZONE INDUSTRIELLE IBN KHALDOUN CITE ETTAHRIR 2042

TUNISIA

Certification Mark See Annex 1

Certified Product Switches for Appliances

Model 1300 Series

See page 2 for additional Information

Trademark ARCOLECTRIC, Arcolectric, ARCOLECTRONIC, BULGIN,

B BULGIN

Ratings 250 Vac 16(6) A 1E4 T125

250 Vac 16(4) A 1E4 T125 250 Vac 16/150 A 1E4 T125

Tested acc. to EN 61058-1-1:2016, EN IEC 61058-1:2018

Test Report No. NC32742-4790149894-3 ORIGINAL issued on 2022-06-24

NC32742-4790149894-4 ORIGINAL issued on 2022-06-24

Additional Information See page 2 for additional information

Certification Manager Jan-Erik Storgaard This is to certify that representative sample(s) of the Product described herein ("Certified Product") have been investigated and found in compliance with the Standard(s) indicated on this License, in accordance with the ENEC Requirements. The Designated License holder is entitled to use the ENEC 15 Mark (as shown in annex 1) for the Certified Product manufactured at the production site(s) identified above in accordance with the ENEC Mark Service Agreement including without limitation the ENEC Mark Testing and Certification Services Service Terms. Only those Products bearing the ENEC Mark should be considered as being covered by UL's ENEC Mark Service. This License shall remain valid unless terminated earlier in accordance with the Service Agreement including without limitation if the Standard identified on this License is amended or withdrawn prior the Date of Withdrawal of conflicting Standard(s).

Certification Body

UL International Demko A/S, Borupvang 5A, DK-2750 Ballerup, Denmark, Tel. +45 44 85 65 65, info.dk@ul.com www.ul.com



ENEC LICENSE

License No. ENEC-04084

Page 2/3

Date of Issue 2022-06-27

Additional Model(s):

Series: 1300 Series, (C, H or T, f/b 1300, 1330, 1350 or 1353, f/b Any letter, f/b Any letter)

Additional information:

Model 1300 Series, Rocker Switch for class II appliances

Full disconnection, Quick-Connect, Solder terminals, Uimp2500 V, PTI 175V, IP40, pollution degree 2, glow wire 850°C.


Certification Body

This is to certify that representative sample(s) of the Product described herein ("Certified Product") have been investigated and found in compliance with the Standard(s) indicated on this License, in accordance with the ENEC Requirements. The Designated License holder is entitled to use the ENEC 15 Mark (as shown in annex 1) for the Certified Product manufactured at the production site(s) identified above in accordance with the ENEC Mark Service Agreement including without limitation the ENEC Mark Testing and Certification Services Service Terms. Only those Products bearing the ENEC Mark should be considered as being covered by UL's ENEC Mark Service. This License shall remain valid unless terminated earlier in accordance with the Service Agreement including without limitation if the Standard identified on this License is amended or withdrawn prior the Date of Withdrawal of conflicting Standard(s).



Annex 1 to License No. ENEC-04084

Annex of the form of the Mark



15 is the identification number of the Certification Body

Size of the mark:

The size of the mark may be reduced on the condition that it remains legible and that the ratio b/a=1,7 is kept.

Certification Body

This is to certify that representative sample(s) of the Product described herein ("Certified Product") have been investigated and found in compliance with the Standard(s) indicated on this License, in accordance with the ENEC Requirements. The Designated License holder is entitled to use the ENEC 15 Mark (as shown in annex 1) for the Certified Product manufactured at the production site(s) identified above in accordance with the ENEC Mark Service Agreement including without limitation the ENEC Mark Testing and Certification Services Service Terms. Only those Products bearing the ENEC Mark should be considered as being covered by UL's ENEC Mark Service. This License shall remain valid unless terminated earlier in accordance with the Service Agreement including without limitation if the Standard identified on this License is amended or withdrawn prior the Date of Withdrawal of conflicting Standard(s).

